Sanitized Copy Approved for Release 2010/08/27 : CIA-RDP80T00246A038100020001-6

# PROCESSING COPY

#### REPORT REPORT INFORMATION INFORMATION

	SECRET	transmission or revelation of which in any manner to an unauthorized		
UNTRY	East Germany	REPORT		
ВЈЕСТ	Reconstruction at Stendal Airfield	DATE DISTR.	<b>1</b> 8 <b>0C</b> T 19	57
		NO. PAGES	1	
		REQUIREMENT NO.	RD	
TE OF		REFERENCES		50X1-HU
O. CE & IE ACQ.				50X1-HU
	Stendal airfield which gives informa (1) Runway/Taxiway Details, (2) Fif	tion under the	following he	report on adings: (3) Target
	(1) Runway/Taxiway Details, (2) Fir	Cymmeser wide i	metion Unit	(b) Excavation
	Date, (4) Air Traffic Control Tower, in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	er installation
	Date, (4) Air Traffic Control Tower, in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9) and (11) SAF Occupation.	tion of Former	Luitwaire Fu	er installation
	in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	er installatio
	in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	er installatio
	in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	er installatio
	in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	er installatio rfield Hangars
	in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	er installatio rfield Hangars
	in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	er installatio
	in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	er installatio
	in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	er installatio
	in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	er installatio
	in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	er installatio
	in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	er installatio
	in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	er installatio
	in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	er installatio
	in NE Corner of Airfield, (7) Renova (8) Permanent Water Pump House. (9)	tion of Former	Luitwaire Fu	50X1-HUM

REPORT INFORMATION REPORT

INFORMATION

	• •	Sanitized Copy Approved for Release 2010/08/27 : CIA-RDP80T00246A0381000	)20001-6
		50X1-HUM	
		EAST GERMANY	
		AIR	
		STENDAL AIRFIELD - Reconstruction progress as at 20 Sep 57	, <del>-</del>
			50X1-HUM
			30X1-110W
1.	(a)	RUNWAY/TAXIWAY DETAILS	
	(a)	The replacement of the faulty sections in the runway has now bee completed and the northern parallel taxiway has been fully concret the runway and the four transverse tracks have all bee cleaned by a special mechanical sweeper, brought to the airfield feast BERLIN.	ed.

MARKET?

- <sup>2</sup> - 50X1-HUM

#### 3. TARGET DATE

The target date set by the Russian authorities for the completion of all concreting on the airfield has been set for 30 Sep 57. The BAU UNION BRANDENBURG authorities anticipate that this date will be met - failing any faults appearing in the taxiway and other newly laid surfaces.

#### 4. ATR TRAFFIC CONTROL TOWER

- (a) The former Air Traffic Control Tower located at MR 91253570 is being evacuated by the BAU UNION BRANDENBURG, who have been using it as a headquarters site. This building is in a very good state of repair and is centrally heated.
- (b) From the upper floor of this building there is a clear, unobstructed view of the airfield landing surface in an easterly and southerly direction only.

  The western end of the new runway is obscured by the sparsely wooded area located around the mixing site at MR 90753530, as well as by the distinct fall-away of the runway at this end.

50X1-HUM

SECRET



- 3 -

SEGAET

50X1-HUM

## 5. S.A.F. CONSTRUCTION UNIT

A small S.A.F. construction unit arrived on the airfield during early September 1957. This unit, with its heavy grading equipment and bulldozers, is engaged on levelling and preparing the ground adjoining the runway and taxiway/transverse tracks for grass seeding at a later date.

#### 6. EXCAVATION IN NE CORNER OF ATRFIELD

The previously reported excavation located at MR 91853575 has been abandoned and is now being used as a dump for debris, etc. from the runway area. No other excavations have been observed anywhere in the airfield built-up area or landing area.

#### 7. RENOVATION OF FORMER LUFTWAFFE FUEL INSTALLATIONS

The BAU UNION MAGDEBURG has been sub-contracted by the BAU UNION BRANDENBURG to undertake the overhauling of the existing former Luftwaffe underground fuel storage tanks and their associated underground pipelines. The development of the main airfield fuel depot on the site of the existing mixing site will begin as soon as concreting has been completed and the associated mixing equipment and cement storage shed have been removed. The wooded area situated in the NW corner of the airfield remains inactive and there are no signs of any development or construction of any sort.

#### 8. PERMANENT WATER PUMP HOUSE

50X1-HUM

There is a permanent underground water pump house located approximately south of and approximately mid-way along the runway. The main water supply from STENDAL passes through this pump house, the pipe lines (details unknown) proceeding under the runway in the direction of the mixing site and then onwards to the airfield built-up area.

There is an alternative direct underground water pipeline extending between STENDAL and the airfield built-up area, this system proceeding along the eastern perimeter of the airfield.

### 9. AIRFIELD RAIL SPUR

50X1-HUM

At the terminal of the airfield rail spur at approximately MR 908353 there is an extensive concrete ramp (see insert to main sketch attached).

This final portion of railway track which extends beyond the mixing site at MR 90753530 appears to be of a permanent construction - the sleepers being of wood in good condition and the track is properly ballasted.

### 10. AIRFIELD HANGARS

- (a) The two former Luftwaffe aircraft hangars located at MRs 910357 and 91353575 appear to be fully serviceable. They both have curved roofs and the main doors are of the folding concertina type. The overhead cranes extending along the inside of each hangar have been repaired and a maximum carrying weight of 3000 kilos is painted on the wall below.
- (b) Extending along both sides of each hangar there is a line of small offices, light workshops, battery charging rooms, etc.
- (c) No new construction is currently being undertaken anywhere in the main built-up area of the airfield.



•	itized Copy Approved for F	WWW.			
•	•				
		- 4 -	- 4 -		
			PET		
Ll.	S.A.F. OCCUPATION			50X1-HUM	
E corner	Three green-coloured of the airfield landi	helicopters hav ng area on nume	e been observed rous occasions	parked in the luring Septemb	er '57.
		**************************************			

50X1-HUM

SFFDET

WAS STORE

Sanitized Copy Approved for Release 2010/08/27 : CIA-RDP80T00246A038100020001-6

